MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:

FLYWHEEL RESURFACING

NO.	TSB-93-21-001
DATE	April, 1993
MODEL	All

PURPOSE

Comments have been received from service technicians requesting flywheel resurfacing limits. In response, flywheel resurfacing is **NOT RECOMMENDED** for any flywheel when resurfacing would require more than 0.5 mm (0.013 in) of material to be removed. During clutch repairs, if a technician encounters a flywheel where resurfacing would exceed 0.5 mm (0.013 in) of material removal for a smooth surface, replace the flywheel.

Copyright 1993
Mitsubishi Motor Sales of America, Inc.
All Rights Reserved

Index # 033563

FILE UNDER: Group 21 Clutch in the Dealer Service Information Binder (1244)

CIRCULATE TO:

- ☐ GENERAL MANAGER
- ☑ PARTS MANAGER
- ☑ TECHNICIAN
- ☐ SERVICE ADVISOR
- ☑ SERVICE MANAGER
- ☐ WARRANTY PROCESSOR
- ☐ SALES MANAGER